

# Brugervejledning

Analyseresultater på internet

Lab Advisor Alert

Internettadressen er [www.statoil.dk/olieanalyser](http://www.statoil.dk/olieanalyser)

Log in to your oil analysis account.

User Name:

Password:

**LOGIN**

**Indsæt  
User name og  
Password**

Home :: Report Search :: Order Kits :: Sample Registration :: Client Administration :: Contact Us :: FAQ :: News :: Logout ::

Basic Search  
Advanced Search  
Unread Reports

## Welcome to the oilanalysis site

Tryk på  
Basic  
Search

### Recent Reports

-  [ 0 Reports not read ]  
[ [View Unread Reports](#) ] - [ [Mark all as read](#) ]
-  [ 0 Reports not read ]  
[ [View Unread Reports](#) ] - [ [Mark all as read](#) ]
-  [ 0 Reports not read ]  
[ [View Unread Reports](#) ] - [ [Mark all as read](#) ]

View  of reports which have not been read...

[Basic Search](#)[Advanced Search](#)[Unread Reports](#)

## Basic Report Search

Customer No

Sample No

System ID

-> fra analyserekvisition

-> fra analyserapport

-> fra preregistrering (findes på analyserapport)

Home :: Report Search :: Order Kits :: Sample Registration :: Client Administration :: Contact Us :: FAQ :: News :: Logout ::

Basic Search  
Advanced Search  
Unread Reports

## Welcome to the oilanalysis site

Tryk på  
Advanced  
Search

### Recent Reports

-  [ 0 Reports not read ]  
[ [View Unread Reports](#) ] - [ [Mark all as read](#) ]
-  [ 0 Reports not read ]  
[ [View Unread Reports](#) ] - [ [Mark all as read](#) ]
-  [ 0 Reports not read ]  
[ [View Unread Reports](#) ] - [ [Mark all as read](#) ]

View  of reports which have not been read...

[Basic Search](#)[Advanced Search](#)[Unread Reports](#)

### Advanced Report Search

Date From 1 / Jan / 2006

Date To 23 / Aug / 2006

Company All Clients

Make All Makes

Model All Models

Serial Number

System Description All

System Class All

System ID All System Id's

Oil Brand/Grade ALL

Serious  Caution  Normal 




Reset

Search

Vælg hvilke  
rapporter du vil se

[Download Search Results](#)
[Download PDFs](#)
[Download CSV](#)
[Back](#)

## Search Results

Date	Customer#	Sample#	SystemID	Make	Model	System	Serial #	Client	Action
21/3/2006	NOT GIVEN	2502652	1002953	TB-65-02	TAS 833	XX-65-020	HPU SUBSEA S	STATOIL LUBRI	
Wear appears satisfactory. Insufficient sample to complete analysis. Advise: Monitor at the recommended sampling period. (* not read)									
<a href="#">Add Comment</a>									
<a href="#">View Report</a> <a href="#">Download Report</a> <a href="#">Download CSV</a> <a href="#">View Chart</a> <a href="#">View Schedule</a>									
14/5/2006	N22970	2525428	1398536	*	TURBINE	NO B		STATOIL LUBRI	
Wear appears satisfactory. No contamination evident. Advise: Monitor at the recommended sampling period. Insufficient sample to complete analysis. (* not read)									
<a href="#">Add Comment</a>									
<a href="#">View Report</a> <a href="#">Download Report</a> <a href="#">Download CSV</a> <a href="#">View Chart</a> <a href="#">View Schedule</a>									
11/5/2006	N22969	2525429	1398539	*	TURBINE	NO A		STATOIL LUBRI	
Wear appears satisfactory. No contamination evident. Advise: Monitor at the recommended sampling period. Insufficient sample to complete analysis. (* not read)									

Vælg View Report

## Lab Advisor Alert



Ans: HANNE ZOSEL  
STATOIL NORGE  
LABORATORIET  
1454 FAGERSTRAND  
NORWAY

Make: <b>Motor</b>		Serial No: 2546	
Model: <b>-</b>		Component: MOTOR	
Sample No: 872	Customer No: N10009714	Sampled: 30-Jan-2003	System Volume:
System ID: 1390320	Machine Hrs: Not Given	Received: 30-Jan-2003	Oil Brand: STATOIL MARWAKY 1040

**Diagnosis**  
Elementanalysen tyder på et normalt slitasjenivå. Øvrige analyseverdier er tilfredsstillende.


Sample No	Sample Date	Age of Oil	Oil Condition										Additive Elements (ppm - ICP)				
			W/M Ratio	W/100 Parts	TBN PPM	Water Cont.	Fuel Dil.	Flash Pt PPM	OCF	Soot %	Deg Index	Glycol	Et	Ca	Mg	P	Zn
872	Not Given	-	126	13.0	6.9	<0.1	N	>215	11	0.3	G	N	<1	3118	5	308	263
873	Not Given	-	121	12.0	10.9	<0.1	N	>215	10	0.2	G	N	<1	3827	10	356	311
871	Not Given	-	121	12.9	11.7	<0.1	N	>215	10	0.2	G	N	<1	4144	9	365	334

Sample No	Sample Date	Age of Oil	Elemental Analysis - Contamination & Wear Metals (ppm - ICP)																	
			B	Na	Si	K	Li	Al	Cr	Cu	Fe	Pb	Sn	Mo	Ni	Ti	Ag	Mn	V	Oil Clog
872	Not Given	-	<1	<1	1	<1	<1	<1	<1	<1	<1	<1	<1	<1	<1	<1	<1	<1	<1	<1
873	Not Given	-	<1	<1	1	<1	<1	<1	<1	<1	3	<1	<1	<1	<1	<1	<1	<1	<1	<1
871	Not Given	-	<1	3	1	<1	<1	<1	<1	<1	3	<1	<1	<1	<1	<1	<1	<1	<1	<1

Analysis performed on oil spill at www.statoil.no/spill-oil. For more information go to www.statoil.no or call us at 800 900 900.

Key: Normal Caution Critical



ULL STELLA HOELDM

Location: **-**

Signed: **-**  
Reference: **19417451017EXAMPSUNE**  
Date: **15/01/2004**

Tel:  
Fax:  
Email:

Friction Fighters™

**STATOIL**



**Download Search Results**
[Download PDFs](#)
[Download CSV](#)
[Back](#)

Vælg View Chart

## Search Results

Date	Customer#	Sample#	SystemID	Make	Model	System	Serial #	Client	Action
21/3/2006	NOT GIVEN	2502652	1002953	TB-65-02	TAS 833	XX-65-020	HPU SUBSEA S	STATOIL LUBRI	

Wear appears satisfactory. Insufficient sample to complete analysis. Advise: Monitor at the recommended sampling period. (\* not read)

[Add Comment](#)

[View Report](#)
[Download Report](#)
[Download CSV](#)
[View Chart](#)
[View Schedule](#)

14/5/2006	N22970	2525428	1398536	*	TURBINE	NO B		STATOIL LUBRI	
-----------	--------	---------	---------	---	---------	------	--	---------------	--

Wear appears satisfactory. No contamination evident. Advise: Monitor at the recommended sampling period. Insufficient sample to complete analysis. (\* not read)

[Add Comment](#)

[View Report](#)
[Download Report](#)
[Download CSV](#)
[View Chart](#)
[View Schedule](#)

11/5/2006	N22969	2525429	1398539	*	TURBINE	NO A		STATOIL LUBRI	
-----------	--------	---------	---------	---	---------	------	--	---------------	--

Wear appears satisfactory. No contamination evident. Advise: Monitor at the recommended sampling period. Insufficient sample to complete analysis. (\* not read)

Select the Analyses to chart and click the 'Next' button.


Next

<input type="checkbox"/> Na	<input type="checkbox"/> Si	<input type="checkbox"/> Al	<input type="checkbox"/> Cr	<input type="checkbox"/> Cu	<input type="checkbox"/> Fe
<input type="checkbox"/> Pb	<input type="checkbox"/> Sn	<input type="checkbox"/> Mo	<input type="checkbox"/> Mn	<input type="checkbox"/> Ba	<input type="checkbox"/> Ca
<input type="checkbox"/> Mg	<input type="checkbox"/> P	<input type="checkbox"/> Zn	<input type="checkbox"/> B	<input type="checkbox"/> Ni	<input type="checkbox"/> Ti
<input type="checkbox"/> Ag	<input type="checkbox"/> Va	<input type="checkbox"/> V	<input type="checkbox"/> Li	<input type="checkbox"/> PQ	<input checked="" type="checkbox"/> kv40
<input type="checkbox"/> kv100	<input type="checkbox"/> Soot	<input type="checkbox"/> TBN	<input type="checkbox"/> OCI	<input type="checkbox"/> TAN177	<input type="checkbox"/> Water
<input type="checkbox"/> WaterKF	<input type="checkbox"/> Insols10micron	<input type="checkbox"/> ParticleCount4	<input type="checkbox"/> ParticleCount6	<input type="checkbox"/> ParticleCount14	<input type="checkbox"/> TAN

Vælg parametre du vil se  
grafer på

To change your Analysis selection, press the 'Back' button.

Back



[Download Search Results](#)
[Download PDFs](#)
[Download CSV](#)
[Back](#)

## Search Results

Date	Customer#	Sample#	SystemID	Make	Model	System	Serial #	Client	Action
21/3/2006	NOT GIVEN	2502652	1002953	TB-65-02	TAS 833	XX-65-020	HPU SUBSEA S	STATOIL LUBRI	

Wear appears satisfactory. Insufficient sample to complete analysis. Advise: Monitor at the recommended sampling period. (\* not read)

[Add Comment](#)

[View Report](#)
[Download Report](#)
[Download CSV](#)
[View Chart](#)
[View Schedule](#)

14/5/2006	N22970	2525428	1398536	*	TURBINE	NO B		STATOIL LUBRI	
-----------	--------	---------	---------	---	---------	------	--	---------------	--

Wear appears satisfactory. No contamination evident. Advise: Monitor at the recommended sampling period. Insufficient sample to complete analysis. (\* not read)


[Add Comment](#)


[View Report](#)
[Download Report](#)
[Download CSV](#)
[View Chart](#)
[View Schedule](#)

11/5/2006	N22969	2525429	1398539	*	TURBINE	NO A		STATOIL LUBRI	
-----------	--------	---------	---------	---	---------	------	--	---------------	--

Wear appears satisfactory. No contamination evident. Advise: Monitor at the recommended sampling period. Insufficient sample to complete analysis. (\* not read)

**Vælg View Schedule**  
(for at se hvornår tidligere prøver er blevet udtaget)





< Previous 13    Next 13 >



Tryk print

Location : *		ClientRef :STATEXAM	
Machine : /*			
Component : MOTOR			
Reference : 2346		/ STATEXAM / 784174	

<input type="checkbox"/>	STATOL NORSE * 1189302 #784174 MOTOR (3) 2346	STATEXAM * 1189302 #784174 MOTOR (3) 2346	<input type="checkbox"/>	STATOL NORSE * 1189302 #784174 MOTOR (3) 2346	STATEXAM * 1189302 #784174 MOTOR (3) 2346
Sample Date	Oil/Water	Oil/Water	Top-Up (L)	Sample Date	Oil/Water
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

<input type="checkbox"/>	STATOL NORSE * 1189302 #784174 MOTOR (3) 2346	STATEXAM * 1189302 #784174 MOTOR (3) 2346	<input type="checkbox"/>	STATOL NORSE * 1189302 #784174 MOTOR (3) 2346	STATEXAM * 1189302 #784174 MOTOR (3) 2346
Sample Date	Oil/Water	Oil/Water	Top-Up (L)	Sample Date	Oil/Water
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

<input type="checkbox"/>	STATOL NORSE * 1189302 #784174 MOTOR (3) 2346	STATEXAM * 1189302 #784174 MOTOR (3) 2346	<input type="checkbox"/>	STATOL NORSE * 1189302 #784174 MOTOR (3) 2346	STATEXAM * 1189302 #784174 MOTOR (3) 2346
Sample Date	Oil/Water	Oil/Water	Top-Up (L)	Sample Date	Oil/Water
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

<input type="checkbox"/>	STATOL NORSE * 1189302 #784174 MOTOR (3) 2346	STATEXAM * 1189302 #784174 MOTOR (3) 2346	<input type="checkbox"/>	STATOL NORSE * 1189302 #784174 MOTOR (3) 2346	STATEXAM * 1189302 #784174 MOTOR (3) 2346
Sample Date	Oil/Water	Oil/Water	Top-Up (L)	Sample Date	Oil/Water
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

<input type="checkbox"/>	STATOL NORSE * 1189302 #784174 MOTOR (3) 2346	STATEXAM * 1189302 #784174 MOTOR (3) 2346	<input type="checkbox"/>	STATOL NORSE * 1189302 #784174 MOTOR (3) 2346	STATEXAM * 1189302 #784174 MOTOR (3) 2346
Sample Date	Oil/Water	Oil/Water	Top-Up (L)	Sample Date	Oil/Water
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

**NB! Bruk etiketter størrelse 105x37 mm (16 stk pr. ark)**

For at se  
historik over  
lang tid tryk

Download  
CSV

Home Report Search Order Kits Sample Registration Client Administration Contact Us FAQ News Logout




Download Search Results

Download PDFs

Download CSV

Back

## Search Results

Date	Customer#	Sample#	SystemID	Make	Model	System	Serial #	Client	Action
21/3/2006	NOT GIVEN	2502652	1002953	TB-65-02	TAS 833	XX-65-020	HPU SUBSEA S	STATOIL LUBRI	
Wear appears satisfactory. Insufficient sample to complete analysis. Advise: Monitor at the recommended sampling period. (* not read)									
<a href="#">Add Comment</a>									
<a href="#">View Report</a> <a href="#">Download Report</a> <a href="#">Download CSV</a> <a href="#">View Chart</a> <a href="#">View Schedule</a>									
14/5/2006	N22970	2525428	1398536	*	TURBINE	NO B		STATOIL LUBRI	
Wear appears satisfactory. No contamination evident. Advise: Monitor at the recommended sampling period. Insufficient sample to complete analysis. (* not read)									
<a href="#">Add Comment</a>									
<a href="#">View Report</a> <a href="#">Download Report</a> <a href="#">Download CSV</a> <a href="#">View Chart</a> <a href="#">View Schedule</a>									
11/5/2006	N22969	2525429	1398539	*	TURBINE	NO A		STATOIL LUBRI	
Wear appears satisfactory. No contamination evident. Advise: Monitor at the recommended sampling period. Insufficient sample to complete analysis. (* not read)									



## Eksempel

	A4	fx 2566354										
	A	B	C	AH	AI	AJ	AK	AL	AM	AN	BH	BL
1	LABNO	CLIQUI	UNITCODE	NA	SI	AL	CR	CU	FE	PB	KV40	APP
2	2566352	STAFAG	800357	5	1	0	0	1	4	1	148.42	10
3	2566353	STAFAG	800358	2	0	0	0	0	3	0	147.235	10
4	2566354	STAFAG	800359	2	0	0	0	0	8	1	148.985	10
5	2566355	STAFAG	800360	2	0	0	0	0	1	1	150.949	10
6	2566356	STAFAG	800359	2	0	0	0	0	2	0	153.033	10
7	2566357	STAFAG	800359	2	3	1	0	6	16	0	133.696	70
8	2566358	STAFAG	800361	1	0	0	0	0	2	0	149.807	20
9	2566359	STAFAG	800362	1	0	0	0	2	27	1	110.7	70
10	2566360	STAFAG	800363	1	0	0	0	0	2	1	158.877	10
11	2566361	STAFAG	800361	1	5	0	0	10	36	0	116.324	20
12	2566363	STAFAG	800449	2	0	0	0	0	3	0	150.321	10
13	2566364	STAFAG	800450	2	0	0	0	0	2	0	146.075	10
14												

**Alle data registrert på prøverne valgt under  
Advanced Search vises i Excel format**

[Home](#)
[Report Search](#)
[Order Kits](#)
[Sample Registration](#)
[Client Administration](#)
[Contact Us](#)
[FAQ](#)
[News](#)
[Logout](#)




### Download Search Results

[Download PDFs](#)

[Download CSV](#)




[Back](#)

## Search Results

Date	Customer#	Sample#	SystemID	Make	Model	System	Serial #	Client	Action
21/7/2006	NOT GIVEN	2566365	1413466		*	SWING KRA	SORKRAM	STATOIL LUBRI	
Too much water to give reliable result. Advise: Action should be taken to correct. (* not read)									
<a href="#">Add Comment</a>									
<a href="#">View Report</a> <a href="#">Download Report</a> <a href="#">Download CSV</a> <a href="#">View Chart</a> <a href="#">View Schedule</a>									
14/1/2006	N23547	2457783	1374960	LIEBHERR	170109 H	GEAR	2457783	STATOIL LUBRI	
Visible debris present. Wear appears satisfactory. Advise: Resample at the next service intervention. (* not read)									
<a href="#">Add Comment</a>									
<a href="#">View Report</a> <a href="#">Download Report</a> <a href="#">Download CSV</a> <a href="#">View Chart</a> <a href="#">View Schedule</a>									
17/1/2006	N23550	2457781	1374958	LIEBHERR	SWING KR	GEAR	2457781	STATOIL LUBRI	
Visible debris present. Wear appears satisfactory. Advise: Resample at the next service intervention. (* not read)									
<a href="#">Add Comment</a>									

Tilføj egne kommentar

Home Report Search Order Kits Sample Registration Client Administration Contact Us FAQ News Logout

<a href="#">View Report</a> <a href="#">Download Report</a> <a href="#">Download CSV</a> <a href="#">View Chart</a> <a href="#">View Schedule</a>									
21/7/2006	NOT GIVEN	2566361	1413369	*	FORD	OLJEPROVE SO	STATOIL LUBRI		
Viscosity not consistent with stated grade. Wear appears satisfactory. Advise: Monitor at the recommended sampling period. (* not read)									
<a href="#">Add Comment</a>									
<a href="#">View Report</a> <a href="#">Download Report</a> <a href="#">Download CSV</a> <a href="#">View Chart</a> <a href="#">View Schedule</a>									
21/7/2006	NOT GIVEN	2566359	1413370	*	PLANET GB	OLJEPROVE SO	STATOIL LUBRI		
Viscosity not consistent with stated grade. Visible debris present. Wear appears satisfactory. Advise: Resample at recommended sampling interval to follow trends. (* not read)									
<a href="#">Add Comment</a>									
<a href="#">View Report</a> <a href="#">Download Report</a> <a href="#">Download CSV</a> <a href="#">View Chart</a> <a href="#">View Schedule</a>									
14/1/2006	N23547	2457783	1374960		LIEBHERR 170109 H GEAR		STATOIL LUBRI		
Visible debris present. Wear appears satisfactory. Advise: Resample at the next service intervention. (* not read)									
<a href="#">View Comment</a>					<a href="#">Edit Comment</a> <a href="#">Delete Comment</a>				
<a href="#">View Report</a> <a href="#">Download Report</a> <a href="#">Download CSV</a> <a href="#">View Chart</a> <a href="#">View Schedule</a>									

Se egen kommentar

Ændre eller slette egen kommentar

Home Report Search Order Kits Sample Registration Client Administration Contact Us FAQ News Logout

Tryk på  
Client Administration




Download Search Results

Download PDFs

Download CSV

Back

## Search Results

Date	Customer#	Sample#	SystemID	Make	Model	System	Serial #	Client	Action
21/3/2006	NOT GIVEN	2502652	1002953	TB-65-02	TAS 833	XX-65-020	HPU SUBSEA S	STATOIL LUBRI	
Wear appears satisfactory. Insufficient sample to complete analysis. Advise: Monitor at the recommended sampling period. (* not read)									
<a href="#">Add Comment</a>									
<a href="#">View Report</a> <a href="#">Download Report</a> <a href="#">Download CSV</a> <a href="#">View Chart</a> <a href="#">View Schedule</a>									
14/5/2006	N22970	2525428	1398536	*	TURBINE	NO B		STATOIL LUBRI	
Wear appears satisfactory. No contamination evident. Advise: Monitor at the recommended sampling period. Insufficient sample to complete analysis. (* not read)									
<a href="#">Add Comment</a>									
<a href="#">View Report</a> <a href="#">Download Report</a> <a href="#">Download CSV</a> <a href="#">View Chart</a> <a href="#">View Schedule</a>									
11/5/2006	N22969	2525429	1398539	*	TURBINE	NO A		STATOIL LUBRI	
Wear appears satisfactory. No contamination evident. Advise: Monitor at the recommended sampling period. Insufficient sample to complete analysis. (* not read)									

Home Report Search Order Kits Sample Registration Client Administration Contact Us FAQ News Logout

Client Details  
Change Password

### Search for Client

Type in search text

Client Name:  e-mail:  Country:  Cliqui

[Search](#)

[1]

Cliqui	Client Name:	Town:	Country:
<a href="#">STAFAG</a>	STATOIL NORGE	FAGERSTRAND	NORWAY

Indsæt % tegn  
for at se flere  
kundekoder  
knyttet til din  
bruger profil

Tryk her for detaljeret  
information

[Home](#) [Report Search](#) [Order Kits](#) [Sample Registration](#) [Client Administration](#) [Contact Us](#) [FAQ](#) [News](#) [Logout](#)

[Client Details](#)

[Change Password](#)

### Client Details

**Client Name:** STATOIL NORGE  
**Address Line 1:** LABORATORIET  
**Address Line 2:**  
**Town:** FAGERSTRAND  
**County:**  
**Country:** NORWAY  
**Post Code:** 1454  
**Contact:** HANNE ZOBEL  
**Tel:** 4722962942  
**Fax:** +47 66918867  
**SAP Sold to No.**

[Unit Details](#)

Tryk på Unit Details

[Back](#)

[Home](#)
[Report Search](#)
[Order Kits](#)
[Sample Registration](#)
[Client Administration](#)
[Contact Us](#)
[FAQ](#)
[News](#)
[Logout](#)

Client Details

[Show Schedule](#)

[Change Password](#)

Make	Model	Serial Number	Machine Type	
	x	1909363	*	<input type="checkbox"/> Sample Print Points Labels
	x	1909364	*	<input type="checkbox"/> Sample Print Points Labels
	x	1909365	*	<input type="checkbox"/> Sample Print Points Labels
	x	1925062	*	<input type="checkbox"/> Sample Print Points Labels
	x	1927648	*	<input type="checkbox"/> Sample Print Points Labels
	x	2004-02325	*	<input type="checkbox"/> Sample Print Points Labels
	x	2004-02326	*	<input type="checkbox"/> Sample Print Points Labels

Password  
kan ændres

Oversikt alle  
systemer

labels kan printes

